



# QUIK-SOL

## For Total Surface Renovating

### DESCRIPTION

**QUIK-SOL** (f.k.a. *PETROMAX*) is a highly effective surface renovator developed for industrial applications where a safer, more powerful solvent is required.

**QUIK-SOL** attacks the molecular structure of dirt, sludge and grime, lifting them away from the surface and emulsifying them for easy rinsing.

### APPLICATIONS

**QUIK-SOL** renovates grimy industrial surfaces, floors, machinery and equipment in automotive repair shops, truck terminals, aircraft hangars, meat packing, printing, industrial, and manufacturing plants, etc.

**QUIK-SOL** removes the flammable hazards of grease and oil build-up.

### PRODUCT BENEFITS

- Heavy Duty renovating power
- Contains no hazardous solvent that produce toxic fumes
- Attacks the molecular structures that bind dirt and grime to surfaces.
- Contains inhibitors to protect renovated metal surfaces
- Gives the action of solvent and the safety of water
- Contains no hazardous VOC's or chlorinated solvent
- Concentrated to reduce storage space (dilution up to 20 :1)
- Non-toxic
- Non-flammable
- Biodegradable
- Saves costly man hours
- Versatile
- Economical

### PHYSICAL PROPERTIES

Appearance.....	Liquid
Colour .....	Purple
Odour .....	Minty-like odour
pH (10%).....	>12
Specific Gravity.....	1.05 ± 0.05
Solubility.....	Water, Complete
Flammability.....	Non-flammable

## APPROVALS

QUIK-SOL is authorized by the U.S Department of Agriculture (USDA) for use in official establishments operating under the Federal meat, poultry, shell egg grading, and egg products inspection programs. Original USDA letter of acceptance is on file in the Home Office..

## DIRECTIONS

Follow the dilution chart below for best results. Spray, mop, or wipe solution onto item to be cleaned. Leave in contact with surface to be renovated for 30 to 60 seconds, then rinse solution and wipe clean.

ITEM	DILUTION
Food Processing Machinery	C
Presses, Punches, Drills	A
Vents, Filters	C
Automotive Parts	A
Elevators, Guard Rails, Safety Equipment	D
Packaging, Vending Equipment	E
Machine Tools, Lathes	A
Pulleys, Winches, Cranes	C
Conveyor Belts, Drive Chains, Loading Ramps	C
Boats, Marine Equipment	B

### DILUTION CHART

	A	B	C	D	E
Parts QUIK-SOL	1	1	1	1	1
Parts Water	1	3	5	7	8

QUIK-SOL must be used in accordance with label directions.

EQUIPMENT: Petrol Pistol / T-3 Sprayer / Trig Mist Sprayer

## STORAGE & SAFETY

Three years, stored in closed original packaging in a cool and dry environment. Harmful if swallowed. Irritant to eyes. Wear gloves and glasses.

*For further information please refer to the Material Safety Data Sheet.*

## PACKAGING

Ref. O-9082-U2	Drum 205L
Ref. O-9082-O2	Pail 25L
Ref. O-9082-J1	Jerry Can 4 x 5L

## WARRANTY

*The information contained herein is presented without guarantee or warranty and the Seller disclaims any liability incurred from the use thereof. Nothing contained herein is to be construed as a recommendation for any use in a commercial process not controlled by the Seller, nor for a use which is in violation of any existing patent, foreign or domestic, or of applicable laws and regulations. THE SELLER MAKES NO WARRANTIES, EXPRESS OR IMPLIED, INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTIES OR MERCHANTABILITY AND FITNESS FOR A PARTICULAR PURPOSE, EXCEPT AS EXPRESSLY STATED IN SELLER'S SALES CONTRACT OR SALES ACKNOWLEDGEMENT FORM.*